

# AA32/AA39



# AA32/AA39

## CO Alarm Verification Test Kit

### OPERATION

The CO verification test kit is used to test that the G series CO sensor is functioning correctly. The kit includes a bottle of 100 ppm CO gas and tubing to connect this to the G series sensor. During testing, the actual concentration of CO flowing into the sensor is diluted by mixing with air.

### INSTALLATION

#### Preparation

Power the sensor for 96 hours prior to verification. Check that the green LED is steadily lit before proceeding. If not, contact technical support.

#### Verification

1. Connect regulator valve to CO bottle.
2. Fill humidifier reservoir half full with water.
3. Screw brass barb onto inlet hole at the bottom right of the sensor. **To protect the sensing element, do not screw brass barb flush to the sensor housing.**
4. Attach 2 ft. tubing between CO bottle and humidifier.
5. Attach 6 ft. tubing between humidifier and brass barb.
6. Slowly open regulator valve.
7. Allow CO gas to flow for 7 minutes. If the sensor is functioning, the red LED will turn on after approximately 3 minutes and remain steadily lit (not flashing).
8. Close regulator valve. Disconnect tubing from brass barb and disassemble the verification test kit.

## NOTICE

- This product is not intended for life or safety applications.
- Do not install this product in hazardous or classified locations.
- Read and understand the instructions before installing this product.
- Turn off all power supplying equipment before working on it.
- The installer is responsible for conformance to all applicable codes.

### PRODUCT IDENTIFICATION

Part Number	Description
AA32	Kit with 100 ppm CO, 17 Liter bottle
AA39	Kit with 100 ppm CO, 103 Liter bottle (requires special regulator valve)

